



Entergy Services, Inc.
Mail Unit L-ENT-24A
639 Loyola Avenue
New Orleans, LA 70113
Tel 504-576-4993
Fax 504-576-5123
e-Mail gpierc2@entergy.com

Gregory D. Pierce
Director Transmission Compliance

July 6, 2011

VIA ELECTRONIC FILING

Kimberly D. Bose, Secretary
Federal Energy Regulatory Commission
888 First Street, N.E.
Washington, D.C. 20426

Re: Entergy Services, Inc.; Docket No. ER05-1065-000
Report of AFC-Related Errors

Dear Secretary Bose:

Pursuant to the Federal Energy Regulatory Commission's ("Commission") April 24, 2006 Order in *Entergy Services, Inc.*, 115 FERC ¶ 61,095 (2006) ("April 24 Order"), Entergy Services, Inc., acting as agent for the Entergy Operating Companies,¹ hereby notifies the Commission it has recently become aware of the following AFC-related error.

In the April 24 Order, the Commission conditionally accepted Entergy's proposal to establish an Independent Coordinator of Transmission ("ICT") for the Entergy System. As the Commission is aware, the Southwest Power Pool, Inc. acts as Entergy's ICT. In the April 24 Order, the Commission imposed an obligation for Entergy to "notify the Commission, the ICT and the Users Group within 15 days if Entergy discovers that it has lost data, or reported inaccurate data, or otherwise believes that it has mismanaged data." See April 24 Order at P 110. Accordingly, Entergy submits the following summary of mismanaged data.

¹ The Entergy Operating Companies include: Entergy Arkansas, Inc., Entergy Gulf States Louisiana, LLC, Entergy Louisiana, LLC, Entergy Mississippi, Inc., Entergy New Orleans, Inc., and Entergy Texas, Inc. The Entergy Operating Companies and Entergy Services, Inc. are referred to collectively herein as "Entergy."

Kimberly D. Bose, Secretary
July 6, 2011
Page 2

Flowgate Definition

On June 22, 2011, Entergy identified that the definition for one flowgate, GRIMZ_GRICO, was incorrect resulting in an inaccurate Line Outage Distribution Factor (LODF) flow for that flowgate in RFCALC. This error was introduced on March 10, 2011, 2:00 PM when manual changes were made to 27 flowgates as a result of the annual review of flowgates. The error was corrected June 22, 2011.

This error may have resulted in incorrect AFC values for this flowgate only. It is not technically feasible to determine the exact impact on AFCs. The error may have potentially resulted in more AFCs available on this flowgate as the flowgate was defined incorrectly in the opposite direction. Additionally, some of the Transmission Service Requests (TSRs), which had this flowgate as one of the top fifteen most limiting flowgates and were processed during the time the error existed, may have had service incorrectly granted. This issue affected TSRs in the Operating and Planning Horizons.

In the event that further information is needed, please do not hesitate to contact the undersigned.

Respectfully submitted,
/s/Gregory D. Pierce
Gregory D. Pierce
Director, Transmission Compliance

cc: Southwest Power Pool, Inc.
ICT Users Group
Service List; Docket No. ER05-1065-000

CERTIFICATE OF SERVICE

I hereby certify that I have this 6th day of July, 2011, served the foregoing document upon the Southwest Power Pool, Inc., the ICT Users Group, and each person designated on the official service list compiled by the Secretary in this proceeding.

/s/ Nicole A. Livaccari

Nicole A. Livaccari
Mail Unit L-ENT-24A
New Orleans, LA 70113
Tel: (504) 576-4296