




6 CY 3PH FLT @ DOUCETTE 138KV  
TRIP DOUCETTE-WOODVILLE CKT#1&WOODVILLE-PID-250 POI CKT#1 AT




6 CY 3PH FLT @ DOUCETTE 138KV  
TRIP DOUCETTE-WOODVILLE CKT#1&WOODVILLE-PID-250 POI CKT#1 AT







6 CY 3PH FLT @ DOUCETTE 138KV  
TRIP DOUCETTE-WOODVILLE CKT#1&WOODVILLE-PID-250 POI CKT#1 AT







6 CY 3PH FLT @ DOUCETTE 138KV  
TRIP DOUCETTE-WOODVILLE CKT#1&WOODVILLE-PID-250 POI CKT#1 AT













6 CY 3PH FLT @ KOUNTZE 138KV  
TRIP KOUNTZE-WARREN CKT#1 AT FLT CLR

FILE: FAULT\_7.OUT




6 CY 3PH FLT @ KOUNTZE 138KV  
TRIP KOUNTZE-WARREN CKT#1 AT FLT CLR

FILE: FAULT\_7.OUT




6 CY 3PH FLT @ KOUNTZE 138KV  
TRIP KOUNTZE-WARREN CKT#1 AT FLT CLR

FILE: FAULT\_7.OUT



6 CY 3PH FLT @ KOUNTZE 138KV  
TRIP KOUNTZE-WARREN CKT#1 AT FLT CLR


FILE: FAULT\_7.OUT






6 CY 3PH FLT @ KOUNTZE 138KV  
TRIP KOUNTZE-MCDONALD-EVADALE;138KV FACILITIES AT FLT CLR

FILE: FAULT\_8.OUT




6 CY 3PH FLT @ KOUNTZE 138KV  
TRIP KOUNTZE-MCDONALD-EVADALE;138KV FACILITIES AT FLT CLR

FILE: FAULT\_8.OUT



6 CY 3PH FLT @ KOUNTZE 138KV  
TRIP KOUNTZE-MCDONALD-EVADALE;138KV FACILITIES AT FLT CLR

FILE: FAULT\_8.OUT



6 CY 3PH FLT @ KOUNTZE 138KV  
TRIP KOUNTZE-MCDONALD-EVADALE;138KV FACILITIES AT FLT CLR

FILE: FAULT\_8.OUT

