



**Entergy Services, Inc.**  
Mail Unit L-ENT-24A  
639 Loyola Avenue  
New Orleans, LA 70113  
Tel 504-576-4993  
Fax 504-576-5123  
e-Mail gpierc2@entergy.com

---

**Gregory D. Pierce**  
Director Transmission Compliance

October 25, 2011

**VIA ELECTRONIC FILING**

Kimberly D. Bose, Secretary  
Federal Energy Regulatory Commission  
888 First Street, N.E.  
Washington, D.C. 20426

Re: Entergy Services, Inc.; Docket No. ER05-1065-000  
Report of AFC-Related Errors

Dear Secretary Bose:

Pursuant to the Federal Energy Regulatory Commission's ("Commission") April 24, 2006 Order in *Entergy Services, Inc.*, 115 FERC ¶ 61,095 (2006) ("April 24 Order"), Entergy Services, Inc., acting as agent for the Entergy Operating Companies,<sup>1</sup> hereby notifies the Commission it has recently become aware of the following AFC-related error.

In the April 24 Order, the Commission conditionally accepted Entergy's proposal to establish an Independent Coordinator of Transmission ("ICT") for the Entergy System. As the Commission is aware, the Southwest Power Pool, Inc. acts as Entergy's ICT. In the April 24 Order, the Commission imposed an obligation for Entergy to "notify the Commission, the ICT and the Users Group within 15 days if Entergy discovers that it has lost data, or reported inaccurate data, or otherwise believes that it has mismanaged data." See April 24 Order at P 110. Accordingly, Entergy submits the following summary of mismanaged data.

---

<sup>1</sup> The Entergy Operating Companies include: Entergy Arkansas, Inc., Entergy Gulf States Louisiana, LLC, Entergy Louisiana, LLC, Entergy Mississippi, Inc., Entergy New Orleans, Inc., and Entergy Texas, Inc. The Entergy Operating Companies and Entergy Services, Inc. are referred to collectively herein as "Entergy."

Kimberly D. Bose, Secretary  
October 25, 2011  
Page 2

### **Exclude Flag**

On October 12, 2011, the ICT identified to Entergy that three long-term Transmission Service Requests (TSRs) did not have the exclude flag in webTrans properly set to “yes” from October 6, 2011 at approximately 15:00 until October 12, 2011 at approximately 16:00 due to a network issue at OATi on October 6, 2011. The exclude flag in webTrans removes the impact of TSRs from the AFC calculations when it is set to “yes”. This flag should be set to “yes” when long-term TSRs are in “study” and have not yet been “accepted”. All three TSRs were submitted by Entergy. The exclude flags for these TSRs were manually changed to “yes” on October 12, 2011.

Entergy believes that this error had the potential to impact the AFC values for the Study Horizon; however, no TSRs impacting the affected timepoints were denied during this time period.

In the event that further information is needed, please do not hesitate to contact the undersigned.

Respectfully submitted,  
/s/Gregory D. Pierce  
Gregory D. Pierce  
Director, Transmission Compliance

cc: Southwest Power Pool, Inc.  
ICT Users Group  
Service List; Docket No. ER05-1065-000

## **CERTIFICATE OF SERVICE**

I hereby certify that I have this 25<sup>th</sup> day of October, 2011, served the foregoing document upon the Southwest Power Pool, Inc., the ICT Users Group, and each person designated on the official service list compiled by the Secretary in this proceeding.

/s/ Nicole A. Livaccari  
Nicole A. Livaccari  
Mail Unit L-ENT-24A  
New Orleans, LA 70113  
Tel: (504) 576-4296